

AMENDMENTS TO THE SPECIFICATION:

Please replace the paragraph beginning at page 15, line 1, with the following rewritten paragraph:

--By forming the above-described loop, the conveyance of recording material 70 to the downstream side of the loop does not have to be synchronized with the recording material 70 being pulled out from the magazine 72. Thus, the printer control section [[60]] 56 drives the motor for synchronized conveyance to rotationally drive the conveyance roller pairs 76, 78, 80 and 82 such that at the downstream side of the loop, the conveyance of the recording material 70 is synchronized with the recording of the image on the recording material 70 by the recording head 60.--